

General Environmental Incident Summary

Incident: 3432 **Date/Time Notice:** 8/22/2014 10:10 **DEM Incident No:**
Responsible Party: Bridger Pipeline LLC

Date Incident: 8/22/2014 **Time Incident:** 06:30 **Duration:** 15 minutes

County: Mountrail **Twp:** 153 **Rng:** 90 **Sec:** 13 **Qtr:** SE SE

Lat: 48.06790 **Long:** -102.18190 **Method:** Interpolation from map

Location Description: Bridger Pipeline LACT unit at the EOG Wayzetta 1-13H.
72nd Ave NW and 45th St NW, Mountrail County.

Submitted By: Bob Dundas **Affiliation:** True Companies

Address: PO Drawer 2360

City: Casper **State:** WY **Zip:** 82602

Received By: Kris Roberts ND DoH

Contact Person: Bob Dundas
PO Drawer 2360
Casper, WY 82602

Distance Nearest Occupied Building: 1140 Feet **Release Contained:** No

Type of Incident: Pipeline Leak

Description of Released Contaminant: Crude oil from LACT pipeline unit.

Volume Spilled: 30.00 barrels **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

Gasket failure and resulting oil spray onto 20 X 200 area on edge of the EOG, Wayzetta 1-13 oil pad lease. A gasket failed between a check valve and flange.

Risk Evaluation:

Low. Spray of oil has been stopped and containment/recovery/cleanup has begun.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Soil is impacted on the EOG - Wayzetta 1-13H lease property

Action Taken or Planned:

It is expected that 10-15 barrels of oil will be recovered. Crew is en-route to remove and dispose of impacted soils. According to the information reported from the field, there is no waters of the state impacted at this time, and the release is confined to the EOG - Wayzetta 1-13 lease property.

Wastes Disposal Location: It is expected that impacted soils will be transported to Clean Harbors Landfill at Sawyer, ND.

Agencies Involved:

Updates

Date: 8/22/2014 **Status:** Reviewed; Followup Required **Author:** Roberts, Kris

Updated Volume: 100.00 barrels

Notes:

Release from a leaking gasket downstream of the LACT building remained within the lease boundaries of EOG Wayzetta 1-13H, but off the wellpad. Followup is necessary.

Date: 8/22/2014 **Status:** Phone/Email Contact **Author:** Roberts, Kris

Updated Volume:

Notes:

Company updated volume lost, based on 45 bbls of liquid oil recovered at time of the report. Spray and flow from the failed gasket remained within the lease boundaries of the Wayzetta 1-13 H location but not completely on the finished pad. Followup is still needed to confirm no off-location impacts.

Date: 11/18/2014 **Status:** Inspected **Author:** Roberts, Kris

Updated Volume:

Notes:

11/18/14 - 13:01 on location. Release from the LACT unit was on the east side of the location. Area has been cleaned, and new erosion control blankets have been placed in the impact area. Landowner also has tilled around the bottom of the toe of the pad in that area. No indication of remaining impacts. No further inspection necessary.